

2430 "E" Street, N. W.
Washington, D. C.
23 September 1953

25X1A9a



1. Signs for Posting Property
2. Location of Picture Moulding

25X1A9a


Dear Mr. [REDACTED]:

With respect to Item 1 of subject, the writer wishes to clarify what apparently is an inconsistency between his letter of 31 August 1953 and Paragraph 31 of the accompanying specifications. Mr. [REDACTED] has now advised that the signs in question will be purchased from a correctional institution in the Washington area and sent to the job, presumably directed to Mr. [REDACTED], for delivery to you at the site. This procedure will be in strict accordance with the indication contained in the specifications. Size and locations of holes to be drilled in the posts will be furnished the Contractor as soon as the information is available.

25X1A9a

Your interpretation of the drawings with respect to Item 2 is correct. Most rooms with plastered walls have picture mouldings. Your suggestion that they be located six inches below the cove mouldings seems reasonable. Please feel free to vary this as you wish to reach a desirable proportion. My suggestion would be to paint both mouldings to match the walls rather than the trim, in order to keep them inconspicuous.

Very truly yours,



25X1A9a